



09/854,269.

C6fC

Docket No.: TESSERA 3.0-139 DIV
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Thomas H. DiStefano

Patent No.: 7,078,819

Issued: July 18, 2006

For: MICROELECTRONIC PACKAGES WITH
ELONGATED SOLDER
INTERCONNECTIONS

Certificate
DEC 07 2006
of Correction

Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 C.F.R. § 1.323

Dear Sir:

Enclosed herewith is a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the Certificate of Correction duly certified.

Dated: November 30, 2006

Respectfully submitted,

By 

Marcus J. Millet
Registration No.: 28,241
LERNER, DAVID, LITTENBERG,
KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090
(908) 654-5000

Attorney for Applicant

DEC 08 2006

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,078,819
APPLICATION NO. : 09/854,269
ISSUE DATE : July 18, 2006
INVENTOR(S) : Thomas H. DiStefano

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover:

In the Abstract, line 6, "but provides thermal" should read -- but can provide thermal --.

Column 1, lines 65-66, "interfaces with the contact pads, produce" should read -- interface with the contact pads, producing --.

Column 2, line 47, "as a" should read -- as an --.

Column 3, line 5, "chip does not" should read -- chip do not --.

Column 3, line 24, "thereon provides" should read -- thereon, provides --.

Column 6, line 1, "and the amount of using" should read -- and mounted using --.

Column 7, line 26, "via-liners can" should read -- via-liners, can --.

Column 9, line 4, "that is in inert" should read -- that it is inert --.

Column 10, line 36, "interposer 201" should read -- interposer 20 --.

Column 10, line 51, "130 SO" should read -- 130 so --.

Column 14, line 2, "so that, said" should read -- so that said --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Marcus J. Millet
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP
600 South Avenue West
Westfield, New Jersey 07090

1
DEC 08 2006